

Hydraulic Pressure Gauges in the Lancair 360



System Unpressurized



After descent from high altitude: Warmer conditions below have caused the High side pressure to rise. Note that the Low side is unaffected.



After parking a cold soaked plane in a warm hangar: The Low side pressure has risen to 1,200 psi. Note the High side circuit is unaffected.